## COBB TUNING AccessPORT

Calibration Notes for 2006-2009 Honda Civic Si

AccessPORT Calibration Anti-Theft Mode v103



## Compatible with AccessPORT

Calibration Name: Anti Theft Mode v103

Latest Calibration Rev: 1.03

Calibration and Calibration Notes Updated: 10/30/09

**Description:** Anti-Theft Mode v103 - Intended for 2006-2009 USDM/CDM Honda Civic Si. This map was designed to not allow the vehicle to

start.






HARDWARE

**Hardware Requirements:** Stock or modified vehicle. <u>Caution</u>: Bypassing the coolant lines from your throttle body assembly will likely cause fuel trims to be excessive (+8 to +11%), more information can be found <u>here</u>.

Fuel Requirement: Minimum 91 octane.





**Power Output:** Vehicle was not tested for power with this calibration.

## Revision Notes:

- 1.03 Updated to match updated performance maps.
- 1.02 Updated to match updated performance maps.
- 1.01 2007-2009 Civic Si calibrations updated to effectively remove speed limiter. The speed limiter does not exist on the 2006 Civic Si.
- 1.00 Original calibration. This map is to not allow the vehicle to start.

## Additional Notes:

This calibration is designed to prevent the vehicle from starting.

CEL Codes Defeated [WHEN USING AS REFLASH MAP] (\*\* means new to latest revision):